This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

図1A




図1B




図1 C






図1 E




図2A




図28




図2C





図2E

図2D

図3A








図 5



吐出ヘッド移動










図7A



垂直打ち(平置き)

図7B



斜め打ち(傾斜) 側面、底面同時形成





図 9






図11





図12



B: 青色蛍光体



12 / 29








図14










図16人






図16B











図19A











図22



素子電圧 VI

図23




図24





図25








図27




図28




図29

